

Defibrillators

1. Woodfold View - South West Ambulance service is responsible for the defibrillator and servicing
2. Telephone Box Corscombe - Friends of the First Responders are responsible for, along with the Parish Council.
3. Village Shop machine - South West Ambulance service is responsible for the defibrillator and servicing
4. Halstock Village Hall machine - Friends of the First Responders are responsible for, along with the Parish Council.
5. West Chelborough - Friends of the First Responders are responsible for, along with the Parish Council.

Defibrillator Report

5th June 2023

1. Inspection at around 9 pm
 - a. Telephone Box Corscombe – fan off.
 - i. Machine ready for action
 - ii. Dick Thorne (Chris C as deputy) looks after this machine.
 - b. Woodfold View – fan off but defib (or cabinet) beeping.
 - i. Battery in defib flat
 - ii. Reported to SWASFT by Geoff Williams but no response as yet.
 - iii. Geoff Williams looks after this Machine
 - c. Village Hall Halstock – fan on
 - i. Returned at 10 pm – fan off.
 - ii. Machine ready for action
 - iii. Peter Brinck looks after this machine.
 - iv. Suggested that he recruits a deputy
 - d. Shop Halstock – no fan fitted to cabinet
 - i. Machine ready for action
 - ii. Old style cabinet which is under cover – so shaded

- iii. Gill Clark looks after this unit
- e. West Chelborough – fan off
 - i. Machine ready for action
 - ii. Susan Soames looks after this machine.
 - iii. Suggested Susan recruits a deputy.
- 2. Design fault with new cabinets
 - a. Fan air inlet / outlet partially blocked by defib.
 - i. Make a small stand for defib so air vent is clear.
 - ii. Have a reflector vest for slipping over the defib case.

Many thanks to Chris C for this update